Fire Department New York Incident Report

Incident Reviewed By

Reviewer 908099 - MEARA THOMAS J. Battalion Chief

Date 11/24/2019

Incident

Incident # 1-0438-0 Status Closed

Incident Date/Time 11/06/2019 08:33:12
Incident Type 111 - Building fire

Box# 0944

Address 10 WESTEND AVE 14B 14 Manhattan

Apartment/Suite 14B Floor 14

Borough 1 - Manhattan

Action Taken1 11 - Extinguishment by fire service personnel

Action Taken2 21 - Search Action Taken3 51 - Ventilate

Rescued (civilians) 0
Evacuated (civilians) 0

Property Use 429 - Multifamily dwelling

Resources

Unit Responsible for Report: BC09

 Unit Type
 92 - Chief officer car

 Action Taken1
 81 - Incident command

 Dispatch Date/Time
 11/06/2019 08:33:34

 Enroute Date/Time
 11/06/2019 08:33:56

 Cleared Date/Time
 11/06/2019 09:05:06

Unit Report By 908099 - MEARA THOMAS J. Battalion Chief

Narrative Incident Narrative

Incident number 11/06/2019-1-0438-0

On Wednesday, November 6, 2019 at 08:33 hours the following units were dispatched to a report of a building fire. The incident location is street address 10 WESTEND AVE Apt. 14B Manhattan NY, 10023. Units responded to report of fire on 14th floor. On arrival units were informed of a fire in apartment 14B with sprinklers operating. L35

Unit Responsible for Report: BC09	
	accessed the apartment and found a sprinkler operating caused by a fire involving a table. E40 stretched precautionary line and L35 overhauled and checked for extension (negative). Building personnel were on scene and VO was issued to restore sprinkler system.
	Primary incident actions taken are as follows: Actions taken - extinguished, searching and ventilation
	Upon arrival Units operated as follows:
	BC09 was dispatched at 08:33 hours and cleared at 09:05 hours. Actions taken - incident command
	E040 arrived at 08:36 hours and cleared at 09:06 hours. Actions taken - hook line up to hydrant, stretch 2 1/2" line and extinguish fire, supplied standpipe system and control traffic
	E023 arrived at 08:39 hours and cleared at 08:50 hours. Actions taken - hook line up to hydrant, supplied standpipe system and control traffic
	E054 arrived at 08:38 hours and cleared at 08:54 hours. Actions taken - hook line up to hydrant, assist engine company with stretching handline and control traffic
	L035 was dispatched at 08:33 hours and cleared at 09:13 hours. Actions taken - perform primary search of fire area, ventilation, salvage and overhaul and material detection, monitoring, sampling, and analysis
	L025 arrived at 08:38 hours and cleared at 09:00 hours. Actions taken - searching, ventilation, material detection, monitoring, sampling, and analysis and control traffic
_	RS01 arrived at 08:38 hours and cleared at 08:50 hours. Actions taken -
	Reporting Member: 908099 THOMAS J MEARA Unit Responsible: BC09
Fire	
Residential Units	300
Buildings Involved	1
Less Than One Acre Burned	Yes
Cause of Ignition	31 - Accidental - Equipment or Heat source failure
Area Of Origin	141 - Living room, family room, den, common room
Heat Source	66 - Candle
Item First Ignited	20 - Furniture, utensils, other
Condition on Arrival	1 - No Flame or Smoke Showing
Factor Contributing To Ignition1	12 - Heat source too close to combustibles.

01/25/2021 Page 2 of 3

Fire		
Suppression Factor1	NNN - None	
Equipment Involved In Ignition	None	
Mobile Property Involved	None	
Structure		
Structure Type	1 - Enclosed building	
Building Type	1 - Fireproof Structure	
Building Status	2 - In normal use	
Floors Above Grade	33	
Floors Belows Grade	2	
Building Length	100	
Building Width	125	
tory of Fire Origin	14	
ire Spread	2 - Confined to room of origin	
Building Type	1 - Fireproof Structure	
tand Pipe System Type	1 - Wet	
tand Pipe System Operation	1 - Standpipe serviceable and used	
tand Pipe System Present	Yes	
etector Presence	1 - Present	
Detector Type	5 - More than one type present	
etector Power	7 - Multiple detectors and power supplies	
Detector Operation	2 - Detector operated	
Detector Effect	1 - Detector alerted occupants, occupants responded	
AES Presence	1 - Present	
AES Type	1 - Wet-pipe sprinkler system	
prinklers	1	
ES Operation	1 - System operated and was effective	
tories Minor Flame	1	
tories Minor Smoke	2	
stories Minor Water	4	

01/25/2021 Page 3 of 3